

Work Permit # SS06-003S

Work Order #
Job# Activity#

☒ Standing Work Permit 1. Work requester fills out this section. Requester: Located in C-A WCC's Log Date: 7-15-06 Ext.: Dept/Div/Group: C-A Department Other Contact person (if different from requester) Ext. Work Control Coordinator: Located in Work Control Log Est. End Date: 7-31-07 Start Date: 8-01-06 Brief Description of Work: ROUTINE ENTRY FOR INSPECTION, DATA COLLECTION. TOURS, OR SKILL OF THE CRAFT TASKS IN POSTED HIGH RADIATION BEAM LINE AREAS AT THE COLLIDER ACCELERATOR DEPARTMENT. Building: Bldg. 912 Switchyard, Target Caves, High Radiation Equipment: Service Provider: Storage Areas 2. WCC, Requester/Designee, Service Provider, and ES&H (as necessary) fill out this section or attach analysis **ES&H ANALYSIS Radiation Concerns** ☐ Airborne ■ None ★ Activation Contamination **⊠**Radiation ☐ Other ☐ Special nuclear materials involved, notify Isotope Special Materials Group Fissionable materials involved, notify Laboratory Criticality Officer Radiation Generating ☐ Radiography ■ Moisture Density Gauges ☐ Soil Density Gauges X-ray Equipment Devices: **▼** None ☐ Ergonomics ☐ Transport of Haz/Rad Material Safety Concerns ☐ Lead* ☐ Confined Space* Explosives ☐ Penetrating Fire Walls ☐ Adding/Removing Walls or Roofs □ Corrosive ☐ Flammable ■ Magnetic Field* □ Pressurized Systems ☐ Asbestos* □ Cryogenic ☐ Fumes/Mist/Dust* ■ Material Handling ☐ Rigging/Critical Lift □ Beryllium* ■ Electrical ☐ Heat/Cold Stress ■ Noise* ☐ Toxic Materials* ■ Non-ionizing Radiation* ■ Biohazard* ■ Elevated Work* ☐ Hydraulic ■ Vacuum ☐ Chemicals* ☐ Oxygen Deficiency* ☐ Other Excavation ■ Lasers* * Does this work require medical clearance or surveillance from the Occupational Medicine Clinic?
Yes No **Environmental Concerns** ■ None ■ Work impacts Environmental Permit No. ☐ Land Use Institutional ☐ Atmospheric Discharges (rad/non-rad) ■ Soil Activation/contamination ■ Waste-Mixed Controls ☐ Chemical or Rad Material Storage or Use ■ Liquid Discharges ■ Waste-Clean ■ Waste-Radioactive ☐ Cesspools (UIC) □ Oil/PCB Management ■ Waste-Hazardous ■ Waste-Regulated Medical ☐ High water/power consumption ■ Waste-Industrial ☐ Underground Duct/Piping □ Spill potential Waste disposition by: □ Other Pollution Prevention (P2)/Waste Minimization Opportunity: No □ Yes **FACILITY CONCERNS** ■ None ☐ Electrical Noise ☐ Potential to Cause a False Alarm ☐ Vibrations ☐ Access/Egress Limitations ☐ Impacts Facility Use Agreement ☐ Temperature Change □ Other ☐ Configuration Control ■ Maintenance Work on Ventilation Systems ■ Utility Interruptions WORK CONTROLS Work Practices ■ None □ Exhaust Ventilation ■ Lockout/Tagout ■ Spill Containment ☐ Security (see Instruction Sheet) ☐ Back-up Person/Watch ☐ HP Coverage □ Posting/Warning Signs ☐ Time Limitation Other ☐ Scaffolding-requires ■ Barricades ☐ IH Survey ■ Warning Alarm (i.e. "high level") inspection Personal Protective Equipment **⋈** None ☐ Ear Plugs ☐ Gloves ☐ Safety Glasses Lab Coat □ Coveralls ■ Ear Muffs ☐ Goggles ☐ Respirator ☐ Safety Harness ☐ Face Shield ☐ Hard Hat ☐ Disposable Clothing ☐ Shoe Covers ☐ Safety Shoes □ Other Permits Required (Permits must be valid when job is scheduled.) ☐ Cutting/Welding ☐ Impair Fire Protection Systems ☐ Digging/Core Drilling ☐ Concrete/Masonry Penetration □ Rad Work Permit-RWP No. RWP-06-03 ☐ Electrical Working Hot ☐ Confined Space Entry Other Dosimetry/Monitoring ☐ Real Time Monitor ■ None ☐ Heat Stress Monitor X TID Self-reading Pencil ☐ Air Effluent ■ Noise Survey/Dosimeter ☐ Waste Characterization Dosimeter ■ Self-reading Digital □ O₂/Combustible Gas ☐ Ground Water ☐ Other Dosimeter ☐ Sorbent Tube/Filter Pump ■ Liquid Effluent ■ Passive Vapor Monitor Training Requirements (List specific training requirements) Radiation Worker I, C-A Facility Specific Safety Training, or C-A Radiobiology Training for NSRL, or C-A Access Training for U-Line. If using the permit when all hazard ratings are low, only the following need to Based on analysis above, the Walkdown Team determines the risk, complexity, and coordination ratings below: sign: (Although allowed, there is no need to use back of form) ES&H Risk Level: WCC: Date: ☐ Low ☐ High Complexity Level: I Low ☐ High Service Provider: Date: Work Coordination: **区** Low ■ Moderate High Authorization to start Date: (Departmental Sup/WCC/Designee)

3. Both work requester and service provider contribute to work plan (use attachments for detailed plans)

Work Plan: (procedures, timing, equipment, and personnel availability need to be addresses)

Estimated dose shall be considered by the WCC prior to each job. Dose estimates will not exceed 20mRem per person per job or 20mRem per entry. This permit is not intended for handling or exposure to tritiated water, unapproved alteration of radiation barriers, or for the potential dispersal of radioactive materials.

A trained Radiation Worker may escort visitors. Permission is required from the C-A ESHQ Division Head (x5272)

READ ALL POSTINGS, MANY LOCATIONS REQUIRE ACTIVATION CHECKS PRIOR TO REMOVING ITEMS

Special Working Conditions:									
Operational Limits Imposed: No entry in to areas greater than 1 R/Hr. Review posted survey of area as applicable.									
Post Work Testing Required: Follow exit requirements on area postings (Activation Check may be Required)									
Job Safety Analysis Required: ☐ Yes ☒ No				Walkdown Required: ☐ Yes ☒ No					
Reviewed by: Primary Reviewer will determine the size of the review team and the other signatures required based on hazards and job complexity. Primary Reviewer signature means that the hazards and risks that could impact ES&H have been identified and will be controlled according to BNL requirements.									
<u>Title</u>	Name (print)			<u>Signature</u>		Life #		Date	
Primary Reviewer	Peter Cirnigliaro		Signature on file			21868		7/21/06	
FS Representative	Paul Berg		Signature on file		ı	19773		7/21/06	
Other									
Other									
Work Control Coordinator	Located in Work Control Log								
Service Provider									
	Review Done: 🗵 in series		☐ team						
4. Job site personnel fill out this section.									
Note: Signature indicates personnel performing work have read and understand the hazards and permit requirements (including any attachments).									
					Contractor Supervisor:				
Workers: Located in Work Control Lo	Life#:		Workers :		Life#:				
Workers are encouraged to provide feedback on ES&H concerns or on ideas for improved job work flow. Use feedback form or space below.									
5. Departmental Job Supervisor, Work Control Coordinator/Designee Conditions are appropriate to start work: (Permit has been reviewed, work controls are in place and site is ready for job.)									
Name: Refer to C-A OPM-AT		·		Signature:	Life#:	Date:			
Name. Refer to 0-A OF WI-AT	, weetings biagrams and rables Signature.				Date.				
6. Departmental Job Supervisor, Work Requester/Designee determines if Post Job Review is required. ☐ Yes ☒No									
Post Job Review (Fill in names of reviewers)									
Name:		Signature:		Life#:		Date:			
Name:		Signature:			Life#:			Date:	
7. Worker provides feedback.									
Worker Feedback (use attached sheets as necessary)									
a) WCM/WCC: Is any feedback required? ☐ Yes ☒ No									
b) Workers: Are there better methods or safer ways to perform this job in the future? No									
8. Closeout: Work Control Coordinator (authorizing dept.) checks quality of completed permit and ensures the work site is left in an acceptable condition									
(WCC can delegate clean up of work area to work supervisor)									
Name:	lame: Signature:			Life#:			Date:		
Comments:									

1.23.3k11e011.doc 2 (04/2005) BNLF3093Erev3/05